





DESIGN RATIONALE

The Half Dome X Posterior Lumbar Interbody Spacer System from Astura Medical delivers a new level of intraoperative flexibility and efficiency by providing infinitely adjustable, simultaneous expansion in height and width of the interbody spacer for a controlled restoration of disc height and optimized fit. These features coupled with acid-etched endplates of the implant, along with an integrated bone graft delivery system within the inserter, maximize bone graft volume and endplate contact. The wide array of implant options and expansive instrumentation delivers a streamlined, efficient procedural sequence that can address even the most difficult pathologies through multiple approaches.

Implant Overview

- Infinitely adjustable, simultaneous expansion in height and width for a controlled disc height restoration and optimized fit
- Integrated bone graft delivery system within the inserter to maximize bone graft volume and endplate contact
- Expansion Ranges
 Heights: 7-10.5, 9.5-14, or 12-17mm

Widths: 9-10


- Lengths: 22, 24, 26, 28, or 30mm
- Lordosis: 3°, 10°, or 15°
- Acid-etched endplates resist migration postoperatively and minimize stress on the vertebral endplates to avoid subsidence
- · Acid-etched surface enhances and increases the efficiency of bone growth





IMPLANT SIZING

Size (mm)	Starting Height (mm)	Expanded Height (mm)	Starting Length (mm)	Expanded Length (mm)	Starting Width (mm)	Expanded Width (mm)	Lordosis Angles (Degrees)
09X22X7.0	7.0	10.5	25.0	22.0	9.0	10.0	3°
09x22x9.5	9.5	14.0	25.9	22.0	9.0	10.0	10°
09x22x12.0	12.0	17.0	26.2	22.0	9.0	10.0	15°
09x24x7.0	7.0	10.5	26.9	24.0	9.0	10.0	3°
09x24x9.5	9.5	14.0	27.9	24.0	9.0	10.0	10°
09x24x12.0	12.0	17.0	28.1	24.0	9.0	10.0	15°
09x26x7.0	7.0	10.5	28.9	26.0	9.0	10.0	3°
09x26x9.5	9.5	14.0	29.8	26.0	9.0	10.0	10°
09x26x12.0	12.0	17.0	30.2	26.0	9.0	10.0	15°
09x28x7.0	7.0	10.5	31.0	28.0	9.0	10.0	3°
09x28x9.5	9.5	14.0	31.9	28.0	9.0	10.0	10°
09x28x12.0	12.0	17.0	32.3	28.0	9.0	10.0	15°
09x30x7.0	7.0	10.5	33.0	30.0	9.0	10.0	3°
09x30x9.5	9.5	14.0	33.9	30.0	9.0	10.0	10°
09x30x12.0	12.0	17.0	34.2	30.0	9.0	10.0	15°









1.0 EXPOSURE

1.1 Identify the affected level using a combination of palpation and fluoroscopy. Using a Midline approach, incise the skin to the fascial layer. Incise the fascia, then use blunt dissection to retract the muscle away from the posterior elements.




2.0 ACCESS

2.1 Decompress the affected neural elements using a combination of laminotomy, facetectomy, and foraminotomy. Attention must be paid to carefully resect the superior portion of the inferior facet back to the wall of the pedicle to allow full access to the disc space. Resection of the facet can be accomplished with an Osteotome (BZ5000000), high-speed burr, and/or Kerrison rongeur. Extreme caution should be used during this step to ensure the neural structures are not compromised during the bone resection process.



3.1 The HALF DOME System offers multiple distraction options; use a combination of the following distraction options to obtain sufficient access to the disc space. Pedicle Screws can be placed above and below the disc space on one side. The screws can be utilized to distract the disc space. Work off the screws by using the Screw Distractor (BZ6300000). Additionally, a Laminar Distractor (BZ6400000) can be utilized in lieu of pedicle screw distraction by applying gentle distraction to the base of the spinous process. Another option for producing distraction is to use Paddle Distractors, which are sized 3-15mm (BZ03000XX), with the Modular T-Handle (EBECABBCZ).



4.0 INTERVERTEBRAL DISC SPACE PREPARATION

4.1 Perform an annulotomy, then remove as much disc material as possible from the disc space. Removal of the intervertebral disc material may be accomplished through the use of Paddle Shavers (BZ04000XX) and Pituitaries provided in the HALF DOME Posterior Lumbar Instrument System. The Paddle Shavers (BZ04000XX) are sized 3-15mm and are to be used with Modular T-Handles. The set includes a 4mm Straight Pituitary (BZ5600000), 6mm Straight Pituitary (BZ5700000), 4mm Up Angled Pituitary (BZ5800000) and 6mm Up Angled Pituitary (BZ5900000). It is imperative that all of the intervertebral disc material is completely removed.





5.0 ENDPLATE PREPARATION

5.1 Endplate preparation can be achieved by the use of the Rasps and Curettes provided in the system. Use a combination of the following instruments to perform a sufficient preparation of the vertebral endplates: Double-Sided Rasps (Straight - BZ5900000 and Angled - BZ6000000) and/or Cup Curettes (Straight - BZ5100000, Right - BZ5200000, Left - BZ5300000, Up - BZ5400000 and Down - BZ5500000). Remove any remaining cartilaginous tissue on the endplates to create a fusion bed of bleeding bone. Additionally, the use of an Osteotome (BZ5000000) can be utilized to remove any offending superior and inferior osteophyte ridges to improve access to the disc space. Extreme caution should be used during this step to avoid neural and vascular compromise.

6.0 IMPLANT SELECTION

6.1 The standard HALF DOME Posterior Lumbar Interbody System includes OTLIF Trial spacers. The OTLIF Trials (BZ6924XXA) are 9mm in width and 24mm in length and are offered in heights ranging from 6-15mm in 1mm increments. The trials are to be used with the Modular Axial Handle (EADCABACZ). Sequentially increase the Trial spacer size until the appropriate height is determined. Utilize fluoroscopy, if necessary, to determine appropriate trial height. Select the corresponding implant size. The height of the Trial spacers is 1-to-1 to the corresponding implant including teeth height.

7.0 IMPLANT PREPARATION AND INSERTION

7.1 Attach the HALF DOME Expandable Implant onto the Expandable Inserter (BZ3100000 or BZ3200000) by first rotating the Distal Knob counter-clockwise to open the implant clamp. Visual confirmation can be achieved by ensuring the line in the window aligns with the line on the internal shaft and the clamps are open. Place the implant clamp into the mating feature on to the proximal portion of the implant. Rotate the knob clockwise until the implant is fully seated. Visual confirmation can be achieved by ensuring the line in the window aligns with the line on the internal shaft. Reset the Indicator to "0" by rotating the Indicator Knob clockwise.

The Expandable Inserter Inner Shaft (BZ3100010-07 or BZ3100020-07) can be used for added strength by inserting the distal end of the Shaft into the proximal end of the inserter and rotating until resistance is achieved. Depress the button to allow for impaction.

Pack the selected HALF DOME Expandable Implant with morselized bone graft material. If necessary, the thecal sac and inferior nerve root may be gently retracted medially with the Nerve Root Retractor (BZ6200000) included in the Posterior Lumbar Instrument System. With the Implant attached to the Expandable Inserter, place the tip of the Implant at the prepared opening, then insert it into the disc space. The Mallet (BZ1600000) may be used to tap the Inserter to facilitate insertion in collapsed disc spaces. The bullet-shaped tip assists in distraction and insertion. Follow the natural curve of the vertebral space when guiding the Implant into the space.





8.0 IMPLANT POSITIONING

- 8.1 Guide the Implant to the proper position. Strive for the following for the final placement of the spacer when using a TLIF Approach:
 - 1. Distal end of the Implant in the anterior 1/3 of the vertebral body
 - 2. Long axis of the Implant oblique to the coronal plane

Strive for the following final placement of the spacer when using a PLIF Approach:

- 1. Bilateral symmetric placement
- 2. Distal end of the Implant located in the anterior 1/3 of the vertebral body




Rotate the Drive Shaft Knob on the Expandable Inserter clockwise to expand the OTLIF spacer. Once the Knob is provisionally tightened, mate the Torque Adapter (BZ3300000) with the Torque-Limiting Handle (EDECGAAZB), then insert into the Drive Shaft Knob. Tighten until the desired height is achieved. The Torque-Limiting Handle will "click" if either the Implant has reached maximum distraction force or height limit. The indicator on the side of the inserter can be used to determine the amount the Implant has expanded.

10.0 INTERVERTEBRAL GRAFT DELIVERY

The HALF DOME Expandable OTLIF spacer may be post-filled with bone graft through the Inserter. First, remove the Inner Shaft (BZ3100010-07 or BZ3100020-07) by unthreading it counter-clockwise. If the Inner Shaft is too tight to unthread by hand, use the Inner Shaft Adapter with the Torque-Limiting Handle (EDECGAAZB).

Place bone graft material into the Drive Shaft Knob, then push the material through the Inserter into the Implant using the Bone Graft Plunger (BZ3400010 or BZ3400020). Care should be taken to not overload the cannula with too much graft material at one time.


Additional allograft or autograft can be packed into the disc space behind and around the spacer using Astura's HALF DOME Bone Graft Delivery Device (BZ170000) and Bone Graft Tamp (BZ6500000) to create a larger fusion mass.





11.0 RADIOGRAPHIC VERIFICATION

Intraoperative radiographs showing a lateral view and an A/P view are suggested. Final placement of the OTLIF spacer is a combination of intraoperative clinical judgment and radiographic appearance.



12.0 SUPPLEMENTAL FIXATION

Supplemental fixation must be used in combination with the HALF DOME Expandable OTLIF spacers to provide sufficient stabilization.



If it is necessary to remove the HALF DOME Expandable OTLIF spacer, the Expandable Implant Retriever (BZ3600000) may be used. First, mate the Implant Retriever Shaft and Screw with the Implant, using the bulleted tip of the screw to align the shaft with the threaded hole in the Implant. Rotate the Shaft until the drive feature is locked with the Implant, then thread the Screw until fully seated. Slide the Implant Retriever Sleeve over the Shaft and Screw and mate the Sleeve's prongs with the sides of the Implant. Attach Expandable Torque Adapter BZ3300000 to preferred Modular Handle and insert over the top of Implant Retriever shaft. Rotate the Shaft counter-clockwise to collapse the Expandable spacer, then pull the spacer out.





HALF DOME EXPANDABLE IMPLANT OFFERING

Part Number	Description	Qty
BH092207B BH092209D BH092212E	OTLIF Spacer, Expandable, 09mmx22mmx7.0-10.5mmx3° OTLIF Spacer, Expandable, 09mmx22mmx9.5-14.0mmx10° OTLIF Spacer, Expandable, 09mmx22mmx12.0-17.0mmx15°	2 2 2





BH092407B	OTLIF Spacer, Expandable, 09mmx24mmx7.0-10.5mmx3°	2
BH092409D	OTLIF Spacer, Expandable, 09mmx24mmx9.5-14.0mmx10°	2
BH092412E	OTLIF Spacer, Expandable, 09mmx24mmx12.0-17.0mmx15°	2



OTLIF Spacer, Expandable, 09mmx26mmx7.0-10.5mmx3°	2
OTLIF Spacer, Expandable, 09mmx26mmx9.5-14.0mmx10°	2
OTLIF Spacer, Expandable, 09mmx26mmx12.0-17.0mmx15°	2
	OTLIF Spacer, Expandable, 09mmx26mmx9.5-14.0mmx10°



BH092807B	OTLIF Spacer, Expandable, 09mmx28mmx7.0-10.5mmx3°	2
BH092809D	OTLIF Spacer, Expandable, 09mmx28mmx9.5-14.0mmx10°	2
BH092812E	OTLIF Spacer, Expandable, 09mmx28mmx12.0-17.0mmx15°	2







HALF DOME EXPANDABLE INSTRUMENTS

Part Number	Description	Qty
BZ31000000	Expandable Inserter, Straight	1
BZ3200000	Expandable Inserter, Offset	1
EDECGAAZB	Egg Inline Torque Handle, 20In-Lbs	1
BZ3100010-07	Expandable Inserter, Inner Shaft Assembly, Straight	1
BZ3100020-07	Expandable Inserter, Inner Shaft Assembly, Offset	1
BZ3300000	Expandable Torque Adapter	1
BZ3700000	Expandable Inner Shaft Adapter	1
BZ3400010	Expandable Bone Graft Plunger, Straight	1
323 100010	z.pa.raasie sone erant rangel, straig.is	·
BZ3400020	Expandable Bone Graft Plunger, Offset	1
BZ3600000	Expandable Implant Retriever	1
BZ350000	Slap Hammer Adapter	1
BZ97000000	Half Dome Expandable Tray	1



HALF DOME IMPLANT SPECIFIC INSTRUMENTS

Part Number	Description	Qty
EBECABBCZ	T-Handle, ¼" Square Quick-Connect, Slap Hammer Impact Cap	2
	эар паншег шірасі Сар	
EADCABACZ	Axial Handle, ¼" Square Quick-Connect,	2
	Slap Hammer Impact Cap	
BZ0300003	Paddle Distractor, 3mm	1
BZ0300004	Paddle Distractor, 4mm	1
BZ0300005	Paddle Distractor, 5mm	1
BZ0300006	Paddle Distractor, 6mm	1
BZ0300007	Paddle Distractor, 7mm	1
BZ0300008	Paddle Distractor, 8mm	1
BZ0300009	Paddle Distractor, 9mm	1
BZ0300010	Paddle Distractor, 10mm	1
BZ0300011	Paddle Distractor, 11mm	1
BZ0300012	Paddle Distractor, 12mm	1
BZ0300013	Paddle Distractor, 13mm	1
BZ0300014	Paddle Distractor, 14mm	1
BZ0300015	Paddle Distractor, 15mm	1
BZ0400003	Paddle Shaver, 3mm	1
BZ0400004	Paddle Shaver, 4mm	1
BZ0400005	Paddle Shaver, 5mm	1
BZ0400006	Paddle Shaver, 6mm	1
BZ0400007	Paddle Shaver, 7mm	1
BZ0400008	Paddle Shaver, 8mm	1
BZ0400009	Paddle Shaver, 9mm	1
BZ0400010	Paddle Shaver, 10mm	1
BZ0400011	Paddle Shaver, 11mm	1
BZ0400012	Paddle Shaver, 12mm	1




HALF DOME IMPLANT SPECIFIC INSTRUMENTS

Part Number	Description	Qty	
BZ0400013	Paddle Shaver, 13mm	1	13 A BETT SAMM SHAVER BESTS
BZ0400014	Paddle Shaver, 14mm	1	14 A SHRYER SHAVER SHAVER
BZ0400015	Paddle Shaver, 15mm	1	15 A SERSO 15MM SHAVER
			Ø SISTEL
BZ692406A	OTLIF Trial, Bayonetted, 6mm	1 / OPT	∆ 1999
BZ692407A	OTLIF Trial, Bayonetted, 7mm	1 / OPT	Δ stilet: OTLIF TRIAL 09-24-08-0*
BZ692408A	OTLIF Trial, Bayonetted, 8mm	1 / OPT	△ 55555 OTHE TRIAL 09-24-09-0°
BZ692409A	OTLIF Trial, Bayonetted, 9mm	1 / OPT	△ 55715 OTLIF TRIAL 09-24-10-0°
BZ692410A	OTLIF Trial, Bayonetted, 10mm	1 / OPT	Δ 55/54 OTLIFTRIAL 09-24-11-0°
BZ692411A	OTLIF Trial, Bayonetted, 11mm	1 / OPT	OTHER TRIAL 09-24-12-0°
BZ692412A	OTLIF Trial, Bayonetted, 12mm	1 / OPT	△ 3555 - OTHETRIAL 09-24-13-0°
BZ692413A	OTLIF Trial, Bayonetted, 13mm	1 / OPT	OTHER TRIAL 09-24-14-0°
BZ692414A	OTLIF Trial, Bayonetted, 14mm	1 / OPT	△ 95749 OTHE TRIAL 09-24-15-0°
BZ692415A	OTLIF Trial, Bayonetted, 15mm	1 / OPT	
BZ1100000	Inserter Driver	1	A TOTAL ASSESSMENT
BZ1200010	Straight Tamp	1	S I STATE OF THE S
			4 SERIO - ANGLED TAMP
BZ1200020	Angled Tamp	1	
BZ1500000	Slap Hammer	1	
BZ1600000	Mallet	1	
BZ4900000	Implant Specific Sterilization Container	1	
			ASTURA



Part Number	Description	Qty
BZ5000000	Osteotome, Straight, 10mm	1
BZ5100000	Cup Curette, Straight, #4, Teeth	1
BZ5100002	Cup Curette, Straight, #2, Teeth	1 / OPT
BZ5200000	Cup Curette, Bayonetted, Right, #4, Teeth	1
BZ5200002	Cup Curette, Bayonetted, Right, #2, Teeth	1 / OPT
BZ5300000	Cup Curette, Bayonetted, Left, #4, Teeth	1
BZ5300002	Cup Curette, Bayonetted, Left, #2, Teeth	1 / OPT
BZ5400000	Cup Curette, Bayonetted, Up, #4, No Teeth	1
BZ5400002	Cup Curette, Bayonetted, Up, #2, No Teeth	1 / OPT
BZ5500000	Cup Curette, Bayonetted, 67.5° Down, #4, No Teeth	1
BZ5500002	Cup Curette, Bayonetted, 67.5° Down, #2, No Teeth	1 / OPT
BZ5600000	Pituitary, Straight, #4, No Teeth	1
BZ5700000	Pituitary, Straight, #6, No Teeth	1





Part Number	Description	Qty
BZ5800000	Pituitary, Up, #4, No Teeth	
BZ5900000	Pituitary, Up, #6, No Teeth	
BZ6000000	Endplate Rasp, Bayonetted, Double-sided, Straight	1
D76100000	Forbild Day Day of the Day to the Anglet	
BZ6100000	Endplate Rasp, Bayonetted, Double-sided, Angled	
BZ6200000	Nerve Root Retractor, 90°	
BZ6300000	Pedicle Screw Distractor	ADDISEQUIRE CONVACION



Part Number	Description	Qty
BZ6400000	Lamina Spreader	1
BZ6500000	Graft Pusher	1
BZ8000000	Cup Currette, Bayonetted, Downgoing, Pointed Tip	1 / OPT
BZ8100000	Modular Lamina Spreader	1 / OPT
BZ1300000	TLIF Counter-Rotation Tamp	1 / OPT
BZ1400000	TLIF Rotation Tamp	1 / OPT
BZ8200000	Box Curette, Straight	1 / OPT
D70400000		4.4657
BZ8400000	Uterine Curette, Bayonetted, Straight, #4, No Teeth	1 / OPT
P7040000	Litarina County Daysonathad Churinht	1./007
BZ8400002	Uterine Curette, Bayonetted, Straight, #2, No Teeth	1 / OPT
P7050000		1./007
BZ8500000	Uterine Curette, Bayonetted, Right, #4, No Teeth	1 / OPT
BZ8500002	Uterine Curette, Bayonetted, Right, #2,	1 / OPT



Part N	lumber	Description	Qty
BZ860	00000	Uterine Curette, Bayonetted, Left, #4, No Teeth	1 / OPT
		No recti	
D7040	20002	Utanina Curatta Davanattad I - ft #2	1 / OPT
BZ860	00002	Uterine Curette, Bayonetted, Left, #2, No Teeth	1/021
BZ890	00006	Rotating Cutter, 6mm	1 / OPT
BZ890	00007	Rotating Cutter, 7mm	1 / OPT
BZ890	00008	Rotating Cutter, 8mm	1 / OPT
D2090	00008	Notating Cutter, Simil	17011
BZ890	00009	Rotating Cutter, 9mm	1 / OPT
BZ890	00010	Rotating Cutter, 10mm	1 / OPT
BZ990	00000	Disc Preparation Sterilization Container	1



1.0 DESCRIPTION: The HALF DOME intervertebral body fusion device is used to maintain disc space distraction in skeletally mature adults requiring an intervertebral body fusion. It is designed to be used in conjunction with supplemental spinal fixation instrumentation. The implant is available in a range of footprints and heights to suit each individual's pathology and anatomical conditions of the patient. The implant has a hollow center to allow placement of autogenous bone graft to promote intervertebral body fusion. Ridges on the superior and inferior surfaces of the device help to grip the endplates and prevent implant migration and/or expulsion.

2.0 MATERIALS: VESTAKEEP® i4R PEEK (ASTM F2026), Tantalum (ASTM F560), TI-6AL-4V ELI (ASTM F136), PEEK-OPTIMA LT120HA (PEEK-OPTIMA HA Enhanced), Nitinol #1 (ASTM F2063).

3.0 CAUTION: Federal law (USA) restricts this device to sale and use by, or on the order of a physician. All implants are intended for single use only. The HALF DOME SYSTEM must not be reused under any circumstances. The HALF ${\sf DOME\,SYSTEM\,is\,not\,a\,stand-alone\,device\,and\,must\,be\,utilized\,in\,conjunction\,with\,supplemental\,posterior\,fixation.}$ These instructions for use are designed to assist in use of the HALF DOME SYSTEM and are not a reference for surgical

4.0 INDICATIONS: The HALF DOME POSTERIOR LUMBAR INTERBODY SYSTEM is indicated for intervertebral body Note: Re-operation or revision may be necessary to correct some of these anticipated adverse events. fusion procedures in skeletally mature patients with degenerative disc disease (DDD) of the lumbar spine at one or two contiguous levels from L1-L2 to L5-S1. DDD is defined as discogenic pain with degeneration of the disc 7.0 WARNINGS AND PRECAUTIONS: The HALF DOME SYSTEM is intended to be used to augment the development confirmed by history and radiographic studies. These DDD patients may also have up to Grade I spondylolisthesis or of a spinal fusion by providing temporary stabilization while a solid fusion mass forms. This device is not intended to retrolisthesis at the involved level(s). HALF DOME SYSTEM implants are to be used with autogenous bone graft and be the sole means of spinal support. The use of autogenous bone graft must be part of the spinal fusion procedure supplemental fixation. Patients should have at least six (6) months of non-operative treatment prior to treatment in which the HALF DOME SYSTEM is utilized. Use of this product without a bone graft or in cases that develop into with an intervertebral cage.

5.0 CONTRAINDICATIONS:

- 5.1 Acute or chronic infectious diseases of any etiology and localization
- 5.2 Signs of local inflammation
- 5.3 Fever or leukocytosis
- 5.4 Morbid obesity
- 5.5 Pregnancy
- 5.6 Metal/polymer sensitivity/allergies to the implant materials
- 5.7 Mental illness, alcoholism, drug abuse
- 5.8 Medical or surgical conditions, which would preclude the potential, benefit of spinal implant surgery
- 5.9 Grossly distorted anatomy due to congenital abnormalities
- 5.10 Rapid joint disease, bone absorption, osteopenia, and/or osteoporosis. Osteoporosis is a relative contraindication since this condition may limit the degree of obtainable correction, the amount of mechanical fixation, and/or the quality of the bone graft.
- 5.11 Any medical or surgical condition which would preclude the potential benefit of spinal implant surgery.
- 5.12 Any case not needing a bone graft and fusion or where fracture healing is not required.
- 5.13 Any patient having inadequate tissue coverage over the operative site or where there is inadequate bone stock, bone quality, or anatomical definition.
- 5.14 Any condition that totally precludes the possibility of fusion, i.e. cancer, kidney dialysis.
- 5.15 Any case not described in the Indications.
- 5.16 Any patient unwilling to cooperate with the post-operative instructions.
- 5.17 Any time implant utilization would interfere with anatomical structures or expected physiological performance, or if the patient has grossly distorted anatomy caused by congenital abnormalities.
- 5.18 Symptomatic cardiac disease.
- 5.19 Systemic or terminal illness.
- 5.20 Prior fusion at the level to be treated.

These contraindications can be absolute or relative and must be taken into account by the physician when making surgical decisions. The list above is not exhaustive.

6.0 POSSIBLE ADVERSE EVENTS:

- 6.1 A listing of possible adverse events includes, but is not limited to:
- 6.1.1 Bending or fracture of implant. Loosening of the implant.
- 6.1.2 Implant material sensitivity, or allergic reaction to a foreign body.
- 6.1.3 Infection, early or late.
- 6.1.4 Decrease in bone density due to stress shielding.
- 6.1.5 Pain, discomfort, or abnormal sensations due to the presence of the device.
- 6.1.6 Pressure on the skin from component parts in patients with inadequate tissue coverage over the implant possibly causing skin penetration, irritation, and/or pain. Tissue damage caused by improper positioning and placement of implants or instruments.
- 6.1.7 Post-operative change in spinal curvature, loss of correction, height, and/or reduction.
- 6.1.8 Dural tears.

INSTRUCTIONS FOR USE

- 6.1.9 Loss of neurological function, including paralysis (complete or incomplete), dysesthesias, hyperesthesia, anesthesia, paraesthesia, appearance of radiculopathy, and/or the development or continuation of pain, numbness, neuroma, or tingling sensation.
- 6.1.10 Neuropathy, neurological deficits (transient or permanent), bilateral paraplegia, reflex deficits, and/or arachnoiditis.
- 6.1.11 Loss of bowel and/or bladder control or other types of urological system compromise.
- 6.1.12 Scar formation possibly causing neurological compromise around nerves and/or pain.
- 6.1.13 Fracture, microfracture, resorption, damage, or penetration of any spinal bone and/or bone graft or bone graft harvest site at, above, and/or below the level of surgery.
- 6.1.14 Herniated nucleus pulposus, disc disruption, or degeneration at, above, or below the level of surgery.
- 6.1.15 Interference with radiographic, CT, and/or MR imaging because of the presence of the implants.
- 6.1.16 Graft donor site complications including pain, fracture, or wound healing problems.
- 6.1.17 Atelectasis, ileus, gastritis, herniated nucleus pulposus, retropulsed graft.
- 6.1.18 Hemorrhage, hematoma, seroma, embolism, edema, stroke, excessive bleeding, phlebitis, wound necrosis, wound dehiscence, or damage to blood vessels.
- 6.1.19 Gastrointestinal and/or reproductive system compromise, including sterility and loss of consortium.
- 6.1.20 Development of respiratory problems, e.g. pulmonary embolism, bronchitis, pneumonia, etc.
- 6.1.21 Change in mental status.
- 6.1.22 Non-union (or pseudarthrosis). Delayed union. Mal-union.
- 6.1.23 Cessation of any potential growth of the operated portion of the spine. Loss of spinal mobility or function.
- 6.1.24 Inability to perform the activities of daily living.
- 6.1.25 Paralysis.

a non-union will not be successful. This spinal implant cannot withstand body loads without the support of bone. In this event, loosening, disassembly and/or breakage of the device will eventually occur. Preoperative planning and operating procedures, including knowledge of surgical techniques, proper reduction, and proper selection and placement of the implant are important considerations in the successful utilization of the HALF DOME SYSTEM by the surgeon. Further, the proper selection and compliance of the patient will greatly affect the results. Patients who smoke have been shown to have an increased incidence of non-unions. These patients should be advised of this fact and warned of this consequence. Obese, malnourished, and/or alcohol and/or other drug abuse patients are also not good candidates for spine fusion. Patients with poor muscle and bone quality and/or nerve paralysis are also not good candidates for spine fusion. Patients with previous spinal surgery at the level to be treated may have different clinical outcomes compared to those without a previous surgery. The implantation of the intervertebral body fusion device should be performed only by experienced spinal surgeons with specific training in the use of this device because this is a technically demanding procedure presenting a risk of serious injury to the patient. PHYSICIAN NOTE: Although the physician is the learned intermediary between the company and the patient, the indications, contraindications, warnings and precautions given in this document must be conveyed to the patient.

CAUTION: The selection of the proper size, shape and design of the implant for each patient is crucial to the success of the procedure. The physician should always consider a variety of patient conditions including but not limited to the levels of implantation, patient weight, and patient activity level, which may have an impact on the performance of the intervertebral body fusion device.

The HALF DOME SYSTEM has not been evaluated for safety and compatibility in the MR environment. The HALF DOME SYSTEM has not been tested for heating or migration in the MR environment. The safety of HALF DOME SYSTEM implants in the MR environment is unknown. Scanning a patient who has this device may result in patient injury.

8.0 IMPLANT SELECTION: The choice of proper size, shape, and design of the implant for each patient is crucial to the success of the surgery. Surgical implants are subject to repeated stresses in use, and their strength is limited by the need to adapt the design to the size and shape of human bones. Unless great care is taken in patient selection, proper placement of the implant, and postoperative management to minimize stresses on the implant, such stresses may cause fatigue and consequent breakage or loosening of the device before the healing process is complete, which may result in further injury or the need to remove the device prematurely. The surgeon is responsible for this choice, which is specific to each patient. Overweight patients may be responsible for additional stresses and strains on the device, which can speed up fatigue and/or lead to deformation or failure of the implants. The surgeon must be thoroughly trained with the surgical procedure, instrumentation and implant characteristics prior to performing surgery. The use of dissimilar materials (e.g., titanium and stainless steel) should not be used together because of the risk of galvanic corrosion. HALF DOME SYSTEM components should not be used with components from other manufacturers.

- 9.1 Only patients that meet the criteria described in the indications should be selected.
- $9.2\,Patient\,conditions\,and/or\,predispositions\,such\,as\,those\,addressed\,in\,the\,aforementioned\,contraindications$ should be avoided.
- 9.3 Care should be used in the handling and storage of the implant components. The implants should not be $scratched\ or\ otherwise\ damaged.\ Implants\ and\ instruments\ should\ be\ protected\ during\ storage\ especially\ from$ corrosive environments.

- 9.4 The type of construct to be assembled for the case should be determined prior to beginning the surgery An adequate inventory of implant sizes should be available at the time of surgery, including sizes larger and smaller than those expected to be used.
- 9.5 The surgeon must ensure that all necessary implants and instruments are available and on hand prior to surgery.
- 9.6 Since mechanical parts are involved, the surgeon should be familiar with the various components before using Instruments should never be exposed to cleaning agents containing any peroxides. Users should periodically inspect the equipment and should personally assemble the devices to verify that all parts and necessary instruments are present before the surgery begins. The HALF DOME SYSTEM components are not to be combined with the components from another manufacturer.
- 9.7 All components and instruments should be cleaned and sterilized before use. Additional sterile components should be available in case of an unexpected need.
- 9.8 All sets should be carefully checked for completeness and all components should be carefully checked for lack Instrumentation (AAMI) quideline ST79:2006 according to the following validated cycle parameters: of damage prior to all surgeries.
- 9.9 A surgical technique manual may be obtained from HALF DOME SYSTEM from any of its representatives.

10.0 INTRAOPERATIVE:

- 10.1 Any instruction manual should be carefully followed.
- 10.2 At all times, extreme caution should be used around the spinal cord and nerve roots. Damage to nerves will cause loss of neurological functions.
- 10.3 The implant surfaces should not be scratched or notched, since such actions may reduce the functional
- upper to the lower vertebrae to be fused.
- 10.5 Bone cement should never be used with this device since this material will make removal of the components Administration for the selected sterilization cycle specifications. difficult or impossible and may affect the properties of the implant. The heat generated from the curing process This statement is not required for the parameters listed above. may also cause neurological damage and bone necrosis.
- 10.6 Before closing the soft tissues, all of the devices should be securely seated.
- 10.7 Breakage, slippage, or misuse of the instruments or implant components may cause injury to the patient or the operative personnel.

11.0 POSTOPERATIVE: The physician's postoperative directions and warnings to the patient and the corre sponding patient compliance are extremely important.

- 11.1 Detailed instructions on the use and limitations of the device should be given to the patient. The risk of fatigue
- 11.2 To allow the maximum chances for a successful surgical result: the patient or device should not be exposed to needed or required, please contact using the company information listed below. mechanical vibrations that may loosen the device construct. The patient should be warned of this possibility and instructed to limit and restrict physical activities, especially lifting and twisting motions and any type of 17.0 COMPANY INFORMATION sport participation. The patient should be advised not to smoke or consume alcohol during the bone graft
- 11.3 The patient should be advised of their inability to bend at the point of spinal fusion and taught to compensate for this permanent physical restriction in body motion.
- 11.4 If a non-union develops or if the components loosen and/or break, the device(s) should be revised and/or removed immediately before serious injury occurs. Failure to immobilize a delayed or non-union of bone will $result\ in\ excessive\ and\ repeated\ stresses\ on\ the\ implant.\ By\ the\ mechanism\ of\ fatigue,\ these\ stresses\ can\ cause$ eventual loosening or breakage of the device(s). It is important that immobilization of the spinal surgical site be maintained until firm bony union is established and confirmed by roentgenographic examination. The patient must be adequately warned of these hazards and closely supervised to ensure cooperation until bony union
- 11.5 Any decision to remove the device should take into consideration the potential risk to the patient of a second surgical procedure and the difficulty of initial implant removal.
- 11.6 Any retrieved devices should be treated in such a manner that reuse in another surgical procedure is not possible. As with all orthopedic implants, none of the retrieved HALF DOME SYSTEM components should ever be reused under any circumstances.

12.0 PACKAGING: Packages for each of the components should be intact upon receipt. All sets and components should be carefully checked for completeness and lack of damage prior to use. Damaged packages or products should not be used, and should be returned immediately to ASTURA MEDICAL.

13.0 CLEANING AND DECONTAMINATION: Instruments of the HALF DOME SYSTEM are supplied clean and NOT STERILE, and must be sterilized prior to use.

14.0 CLEANING: All All instruments must first be cleaned before sterilization and introduction into a sterile surgical field. Immediately after the procedure, place the instruments in a tray and cover with a towel moistened with sterile water and transport to decontamination environment. Rinse the instruments under running tap water for a minimum of 1 minute. An enzymatic cleaner bath (soak) or a solution of water and neutral pH detergent are effective in removing organic material from instruments. Use distilled water if possible. Instruments should be fully submerged for at least ten (10) minutes. Instruments must be thoroughly cleaned. Be sure dissimilar metal instruments are separated. Confirm that all cannulated and modular instruments are fully disassembled. Ensure that all cannulas are flushed until cleaning solution runs clear and that all instruments are completely immersed. Use a small brush to remove soil from all surfaces of the instrument while fully immersed in the solution. Remove soil from hinges, jaws, tips, box locks, and ratchets. Never use steel wool, wire brushes, or highly abrasive detergents or cleaners to remove soil from instruments. Rinse instruments under running water for at least one (1) minute to remove solutions. Once instruments are cleaned and disassembled place instruments in an ultrasonic cleaner with warm enzymatic detergent for a minimum of fifteen (15) minutes. If there is any visual contamination, repeat the steps as necessary until the instruments are visually clean. Rinse instruments under running water for at least one (1) minute to remove solutions.

INSTRUCTIONS FOR USE

instruments for corrosion, discoloration, etc., and properly dispose of instruments that show signs of wear and tear. Note: Certain cleaning solutions such as those containing caustic soda, formalin, glutaraldehyde, bleach and/or $other \, alkaline \, cleaners \, may \, damage \, some \, devices, particularly \, instruments; these \, solutions \, should \, not \, be \, used.$

15.0 STERILIZATION: Moist heat sterilization is recommended using the Association for the Advancement of Medical

Method	Cycle	Temperature	Exposure Time	Dry Time
Steam	Prevacuum	270°F(132°C)	4 minutes	30 minutes

Wrap tray with a towel placed between tray and FDA cleared wrap. The Sterility Assurance Level (SAL) is 1×10^{-6} , via the indicated methods. No claims of pyrogenicity are made. Remove all packaging materials prior to sterilization. Use only sterile products in the operative field. Always immediately re-sterilize all implants and instruments used in surgery. This process must be performed before handling or returning to ASTURA MEDICAL. This gravity displacement sterilization cycle is not considered by the Food and Drug Administration to be a standard sterilization 10.4 Autogenous bone grafts must be placed in the area to be fused and the graft should be extended from the cycle. It is the end user's responsibility to use only sterilizers and sterilization wraps, sterilization pouches, chemical indicators, biological indicators, and sterilization cassettes that have been cleared by the Food and Drug

It has not been determined if reprocessing affects the chemical, phase, or structural properties of the hydroxyapatite on the HALF DOME Posterior Lumbar Interbody Spacer.

16.0 PRODUCT COMPLAINTS: Any Health Care Professional, who has any complaints or who has experienced any $dissatisfaction\ relating\ to\ the\ product\ quality,\ durability,\ reliability,\ safety,\ effectiveness\ and/or\ performance,\ should$ notify ASTURA MEDICAL or its representative. Further, if any of the implanted HALF DOME SYSTEM component(s) ever malfunctions, ASTURA MEDICAL or its representative must be notified immediately. If any HALF DOME SYSTEM product ever malfunctions and may have caused or contributed to the death or serious injury of a patient, the and/or breakage of a temporary internal fixation device during postoperative rehabilitation may be increased distributor or ASTURA MEDICAL must be notified immediately by telephone, fax or in writing. For all complaints, if the patient is active, or if the patient is debilitated, demented or otherwise unable to use crutches or other please include the device name, reference number, and lot number of the component(s), your name, address, and such weight supporting devices. The patient should be warned to avoid falls or sudden jolts in spinal position. the nature of the event to help ASTURA MEDICAL understand the cause of the complaint. If further information is



Astura Medical 4949 W Royal Lane Irving, TX 75063 Phone: (496) 501-5530 Email: info@asturamedical.com





